

To: Hoppe, Michael[Hoppe.Michael@epa.gov]; Vaughn, Stephanie[Vaughn.Stephanie@epa.gov]
Cc: BudneySL@cdmsmith.com[BudneySL@cdmsmith.com];
Gary.Foster@CH2M.com[Gary.Foster@CH2M.com];
George.Hicks@CH2M.com[George.Hicks@CH2M.com];
Jennifer.Wilkie@CH2M.com[Jennifer.Wilkie@CH2M.com]; John Rolfe[jrolfe@demaximis.com]; Willard
Potter[otto@demaximis.com]; Robert Law[rlaw@demaximis.com]; Todd King[TKing@gldd.com]
From: Stan Kaczmarek
Sent: Tue 11/26/2013 8:03:06 PM
Subject: Website Report and Environmental Monitoring Plans
20131124_Weekly_CAP.docx

Stephanie and Mike,

Attached is the proposed website report covering production statistics and environmental monitoring results for the week ending November 24. Please advise if it can be posted.

More importantly, please note that there has been no impact to air quality or water turbidity during the capping operation to date, and there is no reason to expect that will be any impact when the placement of the active layer concludes within the next week or when the geo-textile, armoring stone and habitat layer begins to be placed soon after. Accordingly CPG requests that real time air monitoring be suspended after today's air monitoring is concluded.

In addition CPG asks for confirmation that today's (11/26) collection of water quality composite samples at Buoys 2 and 3 will conclude all routine WQMP sampling events. We also request that the turbidity monitoring buoys be allowed to be taken out of the river after the armoring stone has been placed. The only activity remaining after that will be the placement of a thin sand layer on top of the armoring stone by an excavator bucket.

Please contact me if you have any questions.

Stan Kaczmarek, PE
de maximis, inc.
186 Center Street, Suite 290
Clinton, NJ 08809
(O) (908) 735-9315
(C) (973) 978-9621